



Mine Name	Mine ID	Operator	Activity Type	Activity Date
Moranbah North	MI00750	Anglo Coal (Moranbah North Management) Pty Ltd	Emergency Response	21/02/2021

Mine Record Entry

Executive Summary

Mine Record Entry Detail

Today 21 February 2021, I Inspector of Mines Paul Brown made telephone contact with UMM s.73 Irrelevant inform at 0845hrs regarding a withdrawal from the mine the previous day at approximately 2100hrs 20/02/21, the withdrawal was in response to a Level 3 Active Goaf Spontaneous Combustion trigger and it was believed the inception of the event occurred around 1845hrs 20/02/21 when an overpressure event was reported by the MG605 Longwall face crew.

We discussed the gas data received initially from Goaf Wells and the trending of those results as at the time of our phone call.

I verbally issued a Directive pursuant to section 167 to suspend a re entry into the mine. I informed UMM s.73 Irrelevant that work on any Risk Assessments, Monitoring and Data analysis is not affected, just that no persons are to re-enter the mine until the Directive is met.

Paul Brown
Inspector of Mines