



Mine Name	Mine ID	Operator	Activity Type	Activity Date
Moranbah North	MI00750	Anglo Coal (Moranbah North Management) Pty Ltd	Site Meeting	14/04/2021

Mine Record Entry

Executive Summary

Mine Record Entry Detail

Today 14 April 2021, a meeting was held with the Senior Leadership Team of Moranbah North at the Regional HUB Office located at Grosvenor Mine.

Attending the meeting were:

Shaun Dobson, Deputy Chief Inspector of Coal Mines.

Stephen Smith, Regional Inspector of Coal Mines.

Paul Brown, Inspector of Mines.

s.73 Irrelevant information Moranbah North Mine Operators Representative.

s.73 Irrelevant information SSE.

s.73 Irrelevant information UMM.

s.73 Irrelevant information Production Manager.

s.73 Irrelevant information Technical Services Manager.

s.73 Irrelevant information, Ventilation Superintendent.

The purpose of the meeting was to discuss the Moranbah North mine status and progress on re-entry compliance matters for the current Directive.

A mine update was provided by the SSE focusing on the dewatering of 112 bleeder road, a timeline was discussed for the proposed ventilation change to address the unventilated heading however this is not a fixed date as it is dependant on pump performance.

Discussions on the re-entry compliance matters mainly centred on document MNM_50018.5_TARP13_Spontaneous Combustion TARP for an Active Goaf, version 9, and the supporting technical documents.

Inspectors explained their concerns regarding TARP 13 and again provided examples. Advice was provided on how this may be addressed or at least a process to follow. Of key concern to Inspectors was the Factor of Safety applied within the TARP, metrics identified at all levels including normal being well above all current known text within industry and, the justification supporting the TARP which contained conflicting statements.

Inspectors expressed their concern on how the practice of pro-active Inertisation may corrupt the gas monitoring data, the site needs to provide evidence of how this is accounted for within

the gas data and how it is applied in practice within the gas monitoring system.

IOM Brown explained there is still a number of documents still under review by Inspectors which may still require further discussion pending on the results of the review. IOM Brown stated that while there may be some further work required with re-entry documents, TARP13 is considered to be one of the key documents required to be addressed for the Directive.

Paul Brown
Inspector of Mines

Shaun Dobson
Deputy Chief Inspector of Coal Mines

Stephen Smith
Inspector of Mines

Released by RSPHQ
RTI Act 2009