



Mine Name	Mine ID	Operator	Activity Type	Activity Date
Moranbah North	MI00750	Anglo Coal (Moranbah North Management) Pty Ltd	Postal Mine Record Entry	30/04/2021

Mine Record Entry

Mine Record Entry Detail

Today 30 April 2021, an online meeting was conducted between Inspectors and the Senior Leadership Team of the Moranbah North Mine.

Attending the meeting were:

Shaun Dobson, Deputy Chief Inspector of Mines.

Stephen Smith, Regional Inspector of Mines

Geoff Nugent, Inspector of Mines.

Paul Brown, Inspector of Mines.

Harilal Surendran, Inspector of Mines.

s.73 Irrelevant info, Operators Representative.

s.73 Irrelevant info, SSE.

s.73 Irrelevant info, Technical Services Manager.

s.73 Irrelevant info, Ventilation Superintendent.

The meeting was requested by Mr s.73 Irrelevant info to discuss the mines updated status and progress of responses for the Directive pursuant to section 167 of the Coal Mine Safety and Health Act 1999, given on the 21/02/2021. The Directive was given for a suspension of re-entry into the mine until such time as the SSE can demonstrate an acceptable level of risk.

Responses to Inspectors from the meeting 27/04/21 were only received shortly before commencing today's meeting, it was made clear that not all documents had been read by Inspectors and that prior to calling further meetings Inspectors require time to conduct their reviews.

There were general discussions regarding SHMS documents supporting the re-entry, the current gas monitoring data, water levels at 112 roadway and the management systems required to monitor water, the environmental conditions for 112 roadway regarding methane content, the calibration of gas monitoring systems including integrity testing of Tube Bundle systems, the make-up of the re-entry teams and the inspection process.

On completion of the meeting, an email was sent by IOM Brown to s.73 Irrelevant info and s.73 Irrelevant info at 16:06hrs highlighting the following points:

- Need a system (TARP recommended) for managing the water in 112 road with clear parameters for factor of safety.
- Need the third goaf well data s.73 Irrelevant info requested from s.73 Irrelevant info
- Need difference between goaf well data and tube bundle data explained s.73 Irrelevant info requested from s.73 Irrelevant info
- Require SPW Files for the past 30 days of Tube Bundle Points - S0868, 869, 867,

S01115, SO895, S01116, SO852, S1107, GA012 Tube 10, GA 012 Tube 11, GA 012 Tube 20.

- Copy of Files for Goaf Drainage (RT) for past 30 days Goaf Wells SO868, SO852, SO869.
- We did not discuss the LFI and concerns raised about its compliance to Reg 15 today (mentioned in meeting 27/04/21), if you could provide a response to this by midday Tuesday it would be appreciated.

Paul Brown
Inspector of Mines

Geoff Nugent
Inspector of Mines

Harilal Surendran
Inspector of Mines

Shaun Dobson
Deputy Chief Inspector of Coal Mines

Stephen Smith
Inspector of Mines

Released by RSHQ
RTI Act 2009