



Mine Name	Mine ID	Operator	Activity Type	Activity Date
Moranbah North	MI00750	Anglo Coal (Moranbah North Management) Pty Ltd	Investigation - Continued	07/05/2021

Mine Record Entry

Site Safety & Health Reps Consulted: s.73 Irrelevant information

Executive Summary

Mine Record Entry Detail

Today 7 May 2021 at 1530hrs, Inspector of Mines Paul Brown and Inspector of Mines Geoff Nugent participated in the Re-Entry Inspections of Moranbah North Mine.

Inspector Brown participated with the underground Re-Entry Inspection Teams and Inspector Nugent, participated by auditing the implementation of the Re-Entry Management Plan at the Surface operations offices.

Advice was provided by Inspectors as and when required to individual working groups and IMT. The Re-Entry albeit limited due to shift time constraints was conducted satisfactorily without incident or injury.

Verbal and written notice (section 3.8 of the Mine Re-Entry Plan, MNM_COMP001_Plan) of TARPs not currently in normal status was received during Dayshift 7/05/21.

The Re-Entry continued on Nightshift with Regional Inspector of Mines Stephen Smith in attendance to audit compliance again to the Management Plan.

Paul Brown
Inspector of Mines

Geoff Nugent
Inspector of Mines