



Mine Name	Mine ID	Operator	Activity Type	Activity Date
Goonyella Riverside	MI00568	BM Alliance Coal Operations Pty Ltd	Postal Mine Record Entry	06/08/2018

Vision: Our Industries Free of Safety and Health Incidents

Mine Record Entry

This report forms part of the Mine Record under s68 of the Coal Mining Safety and Health Act 1999. It must be placed in the Mine Record and displayed on Safety Notice Boards.

Note that inspection or audit activities conducted by the Mines Inspectorate are based upon sample techniques. It remains the primary responsibility of Mine Personnel to identify hazards, and risks associated with Operations and ensure those risks are at an acceptable level.

Today I, Mr Cres Bulger (Inspector of Mines) and Mr Les Marlborough (Regional Inspector of Mines) held a Level 3 Accountability meeting with the Maintenance Manager from Goonyella Riverside mine Mr Kevin McDonald. At the request of Mr McDonald, Mr Trevor Steinhardt (Fixed Plant Maintenance Supt at Goonyella Riverside mine) was also present at this meeting.

The purpose of this meeting was to outline the findings and recommendations identified by the mine's inspectorate in their investigation of the Daniel Springer fatality which occurred at Goonyella Riverside mine on the 5th of August 2017. Highlighted within these findings were the areas of individual non-compliance which were identified in the investigation.

The inspectorate would like to thank Mr McDonald and Mr Steinhardt for making themselves available for this meeting

Creswick Bulger
Inspector of Mines

Les Marlborough
Inspector of Mines